

Номенклатура	Свободный остаток
	В базовых ед.
PM 105 (Powerram)	1,000
PME 800 (Powerram)	1,000
PUB PSD/C1 003	1,000
PUB PSD/C1 004	9,000
PUB PSD/C1 006	1,000
TMAS 100-005 (КСИЗ)	2,000
TMAS 100-010 (КСИЗ)	2,000
TMAS 100-020 (КСИЗ)	2,000
TMAS 100-040 (КСИЗ)	2,000
TMAS 100-050 (КСИЗ)	2,000
TMAS 100-070 (КСИЗ)	2,000
TMAS 100-100 (КСИЗ)	2,000
TMAS 100-200 (КСИЗ)	1,000
TMAS 125-010 (КСИЗ)	1,000
TMAS 125-020 (КСИЗ)	1,000
TMAS 125-040 (КСИЗ)	1,000
TMAS 125-050	1,000
TMAS 125-070	1,000
TMAS 125-100	1,000
TMAS 125-200	1,000
TMAS 200-005	1,000
TMAS 200-020	1,000
TMAS 200-025	2,000
TMAS 200-050	1,000
TMAS 200-200	1,000
TMAS 50-005	1,000
TMAS 50-010	2,000
TMAS 50-020	1,000
TMAS 50-025	1,000
TMAS 50-040	2,000
TMAS 50-050	2,000
TMAS 50-050	1,000
TMAS 50-070	2,000
TMAS 50-070	1,000
TMAS 50-100	1,000
TMAS 50-100	1,000
TMAS 50-200	1,000
TMAS 50-200	1,000
TMAS 75-005	1,000
TMAS 75-010	1,000
TMAS 75-020	1,000
TMAS 75-025	1,000
TMAS 75-030	1,000
TMAS 75-040	1,000
TMAS 75-040	1,000
TMAS 75-050	1,000

TMAS 75-070	1,000
TMAS 75-070	1,000
TMAS 75-100	3,000
TMAS 75-200	2,000
TMBS 100E	1,000
TMFN 23-30	3,000
TMFN 30-40	1,000
TMFT 36 C	1,000
TMIP 7-28	1,000
TMMA 80	2,000
TMMP 2X65	4,000
TMMP 3X230	3,000
TWIM 15-BAG	1,000
VGMB WVN701-4	3,000
ГГ Tr260x4 (52E)	1,000